


# Drainage job



## Negotiable

 Mains Plumbers 2004 ltd



 See on [ServiceFinder.co.nz](https://www.ServiceFinder.co.nz)



Customer rung with a blocked drain, we managed to pin point the location and the problem which were tree roots. Once the trench was dug Tyler had the job of removing the old pipe and getting all the tree roots out. New pipe all in ready to be bedded in gravel and backfilled! Job well done!